

Spring Mountain Ranch State Park

North

0 ft 500 ft

TRAIL USE


- Hiking
- Bicycles
- Equestrians
- Dogs on Leash
- No Motor Vehicles

LEGEND

- Bridge
- Parking
- Restroom
- Picnic Area
- Amphitheater
- Ranger Station
- Group Reservation Area
- Park Entrance Information
- Ranch House Visitor Center
- Trail Access Information
- Secondary Trail
- Park Boundary
- Road



Bureau of Land Management



TRAIL ACCESS INFORMATION

Trail Name	Length	Typical Grade	Maximum Grade Standard Ramp is 8.3%	Typical Cross Slope	Maximum Cross Slope	Typical Tread Width	Minimum Clearance Width	Surface Type	Surface Firmness Typical Worst	Surface Stability Typical Worst
Sandstone Canyon Loop	1.2 mi	7.5%	160 ft is 21% - 48%	3.1%	35 ft is 13% - 14%	22 in	14 in	Soil	0.18 0.20	0.49 0.74
Overlook Loop	0.8 mi	6.0%	180 ft is 21% - 32%	3.3%	61 ft is 13% - 16%	36 in	16 in	Soil	0.17 0.18	0.37 0.55
Lake Harriet Loop	0.4 mi	2.0%	65 ft is 11% - 12%	3.5%	111 ft is 9% - 10%	8 ft	8 ft	Aggregate Gravel	0.17 0.17	0.26 0.41
North Ash Grove Loop	0.3 mi	3.6%	137 ft is 9% - 11%	3.2%	52 ft is 9% - 11%	5 ft	3 ft	Crushed Stones	0.17 0.18	0.30 0.34
South Ash Grove Loop	1.4 mi	4.4%	120 ft is 16% - 27%	2.7%	134 ft is 11% - 13%	34 in	16 in	Soil	0.20 0.27	0.69 1.00

Surface Firmness (in)

Surface Stability (in)

WARNING: Trail conditions may have changed since February 2011 when these trails were assessed. Signage created by Beneficial Designs Inc. using trail data collected by a certified trail assessment coordinator.

Funded by the Nevada Recreational Trails Program

Signage by Beneficial Designs Inc. www.beneficialdesigns.com Nevada Office: 775.783.8822

"Designing beyond the norm to meet the needs of all people."